Struck Corporation W51 N545 Stuck Lane PO Box 307 Cedarburg, WI 53074 Phone: (262) 377-3300

Email: parts@struckcorp.com

Text: (262)-233-4292

Abbreviated parts list for the MAGNATRAC MH6000 and many more parts available. **All prices are subject to change daily.** Thank you.

Part#	Description	Price
SK-001164	Seal Kit, #31-cylinder, inside boom, 1 1/2" rod.	\$67.04
SK-001165	Seal kit, #310-cylinder, top of boom, 1 3/4"rod.	\$66.01
K-001166	Seal kit, #671, #29 Cylinder dipper bucket curl.	\$69.98
00029kit-1	#29 Cylinder & Fitting Kit - Cylinder, painted black, fits RH65, BG48, MDB154	\$250.60
00029kit-2	#29 Cylinder & Fitting Kit - Cylinder, painted black, D1060 & D108 Backhoe left & right swing.	\$293.40
00031kit	#31 Cylinder & Fitting Kit - painted black, Yoke to Boom.	\$429.15
00214up	Rear Axle only, unpainted.	\$89.05
00215up	Front Axle only, unpainted.	\$127.65
00232-up	Drive chain shim	\$1.45
00233-Replaced by	#000234 Track tension Spring 5"	\$29.28
00239	Bearing, Oilite, 1-1/8" OD x 7/8" ID	\$5.58
00240	O-Ring, 1-1/8 "OD x 7/8" ID	\$0.36
00241-Replaced by	#000242 Washer, 18 GA x 7/8" ID x 1-1/2" OD	\$0.74
00243B	Bearing, 1-1/4" ID & set screw.	\$20.92
00244	Slotted Spring Pin, 1/4" x 1-1/2" (Used with most 7/8" OD pins and axles).	\$0.78
00252B	Bearing with Collar & Set Screws, 1" ID x 2" OD.	\$16.32
00262-up	Tube, 4" spring stop only, unpainted goes with #000234 black spring.	\$4.46
00303	Seat belt for ROPS 60" Lap belt - black (push button).	\$46.99
00310kit	#310 Cylinder & Fitting Kit - painted black, Top of Boom.	\$473.00
00429	Throttle Control Assembly with nut.	\$25.30
00430	Choke Cable Push/Pull Control.	\$13.86
00441	Neutral safety switch with (2) nuts.	\$15.00
00444	Ignition switch with key, nut, and lock washer.	\$14.03
00444B	Ignition key only, fits #000444 & #001358.	\$2.25
00455B	Hydraulic filter (HE10 ZINGA ,10 micron - spin on element)	\$38.84
00536A	#50H Chain - 56 pitches without Connector link (UPPER Drive Chain)	\$21.38
00536B	#50 Master Connector Link	\$2.88
00616A	Breather cap, for hydraulic tank. 3/4"NPT.	\$24.30
00671kit	#671 Cylinder & Fitting Kit - Cylinder, painted black, fits HL900 Loader arm, D108 bucket curl cylinder, and D108 Stabilizer.	\$304.15
00715	Disk Drive welded assembly with hardened teeth.	\$176.85
00724	Primary Drive Sprocket Assembly, welded & heat treated	\$197.44
01006up	Pump Mounting Hub - 4 Hole type with 2-3/4" hole spacing.	\$128.24
01029-Replaced by	#001029ZZ-kit1 Steel fuel tank assembly	\$272.59
) 1030up	1/2" Track tension rod / bolt.	\$28.87
01044	Track Drive Pump, (Front of Engine).	\$401.26
01045	Attachment Pump, (Rear of Engine).	\$382.00
01090	#80H Chain - 29 Pitches, without connector link (LOWER Drive Chain)	\$47.77
01091	#80 Master connector link	\$10.41
01127A-kit	16" Fan kit (MH7000, MH8000) old fan design is no longer available.	\$127.63
	#004385 Center idler assembly, 4 1/2", with (2) #239 bushings (Uses 5)	\$124.63
01219 Replaced by	#004386 Rear Drive Sprocket (for the track)	\$357.04

001228	Use # 004385, Front idler sprocket (for the track).	\$289.03
001599E-2	***Press Fit w/Smaller Mushroom Head" - CA551X Track pin w/cotter.	\$5.50
001599F	CA551X Inner roller link.	\$12.31
001599H-up	CA551X Outer connector links welded to #004587 track plate	\$37.88
002061	1/8" NPT straight zerk	\$0.97
004354kit	Quick Release Center Axle Kit	\$34.85
004385	Front Idler Sprocket (for the track)	\$289.03
004386	Rear Drive Sprocket (for the track)	\$357.04
004578kit	2021 Heavy-Duty Track Set (CA551X Heavy-Duty Chain without ears)	\$2008.60
TSO40-B	Heavy-duty grouser track shoe kit	\$585.00

Shipping costs will be added to your order amount. We accept Visa, Mastercard, American Express, Discover, Pay Pal and checks with a 2-week waiting period.